



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director  
JOHN R. BAZA  
Division Director

### Inspection Report

Supervisor 10074

Minerals Regulatory Program  
December 27, 2006

**Mine Name:** Soma Quarry  
**Operator Name:** Nephi Sandstone Corp.  
**1250 N 200 W**  
**PO Box 137**  
**Nephi, Ut 84648**  
**Inspector(s):** Tom Munson  
**Other Participants:** none  
**Mine Status:** inactive

**Permit number:** S230065  
**Inspection Date:**  
09/06/2006&10/4/2006  
**Time:** 10 AM

**Weather:** sunny

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

The purpose of these inspections was to determine if a protective berm had been established along the banks of the Sevier River.

#### Directions to Site:

The is located just east of Leamington on the banks of the Sevier river.

#### Inspection Summary:

On 09/06/2006 no berm had been established along the river, so a call was made to Mr. Bruce Evans to determine if and when this work would be accomplished. Another inspection was made on 10/04/2006 and the berm was in place.

#### Conclusions and Recommendations:

The site is inactive at the moment, but no bond is in place for this quarry and a phone call was made to Mr. Evans informing him that a bond for three acres of disturbance or \$12,000 was required as soon as possible.

**Inspector's Signature** Thomas R. Munson

**Date:** 12/27/06

tm:pb

cc: Operator  
GPS map and Photos

O:\M023-Juab\S0230065-Somalinspections\insp-09062006.doc



10/4/2006  
SOMA QUARRY



BERM REPAIRED



9/6 /06

SOMA QUARRY



NO BERM BY THE RIVER



SEVIER RIVER







PORTABLE CRUSHER + PAD





9/6/06



HIGH WALL





Soma A QUARRY  
9/6/06





**Mine Number: S0230065**  
**Mine Name: Soma Quarry**  
**Township 14 S Range 03 W Section 22 SLBM**

Inspection Date Aug. 29, 2006  
 Map Produced by DKS

Acres Disturbed	2.9
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
<b>Total Acres Disturbed</b>	<b>2.9</b>
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

**Legend**  
 All items symbolized in legend may not be appear on map

- |                 |   |
|-----------------|---|
| County Boundary | Township or range Line                    |
| Access          | Township or range line: location doubtful |
| Mine            | Section line                              |
| NonMine         | Section line: location doubtful           |
| Reclaimed       | Disturbed                                 |
| Other           | Regraded                                  |
| Interstate      | Seeded                                    |
| US Route        | Released                                  |
| State Route     | Excluded                                  |
| Primary Route   | PreExisting                               |
| Secondary Route | Prelaw                                    |
| Main Dirt Road  | Bond Area                                 |
| Unimproved Road | SITLA Mineral Leases                      |
| Interchange     | BLM Saleable Minerals                     |
| Trail           | Community Pit                             |
|                 | SITLA Mineral Ownership                   |

DOQ imagery date 2004



0 625  
 Feet  
 1:7,500 1 inch equals 625 feet  
 Verify Scale

Dept. of Natural Resources  
 Division of Oil, Gas, and Mining  
 Mineral Mines Program

Different data sources and input scales  
 may cause misalignment of data layers.  
 This product may not meet DGM  
 standards for accuracy and content.